

KLEEN TANK

RV TANK CLEANING SERVICE
VISIT ASKLEENTANK.COM FOR Q&A'S

SERVICE ORDER & PAYMENT RECEIPT

EMAIL INFO@KLEENTANK.COM
WEB KLEENTANK.COM
TEL 844-KLEENME

SERVICE DATE 5/7/24
START TIME 8
STOP TIME
TECHNICIAN Ward & Ben

CUSTOMER NAME Mike Ward FIRST TIME REPEAT

RV IS: OWNED RENTED RVER IS: PERMANENT VISITING PASSING THROUGH RALLY

TELEPHONE NO. 731-7405984 EMAIL ADDRESS _____

RV PARK Exhart City 4H fair CITY & STATE Croshan, IN SITE NO. 287

RV MAKE Newmar RV MODEL Ventura 3412 RV YEAR 2017

RV TYPE: TRAVEL TRAILER 5TH WHEEL MOTOR COACH OTHER MACERATOR? Y N

CUSTOMER ISSUES: NONE SENSORS ODORS DRAINAGE CLOG OTHER _____

BLACK TANK ADDITIVE USED: NONE KT CAL/PINE OTHER _____

GRAY TANK ADDITIVE USED: NONE KT CAL/PINE OTHER _____

WASTE TANK REPORT

BLACK TANK 1 SERVICED? YES NO MBATH PWDR/COMBO
TANK CAPACITY 45 VERIFIED: CUSTOMER RVUSA MANUF OTHER
INITIAL FLOW GREAT GOOD OKAY FAIR BAD N/A
CLEANING ISSUES SLOW FLOW HEAVY DEBRIS OBSTRUCTION NONE
TANK ODORS GREAT GOOD OKAY FAIR BAD N/A
OVERALL HEALTH/GRADE B Normal Usage

BLACK TANK 2 SERVICED? YES NO MBATH PWDR/COMBO
TANK CAPACITY _____ VERIFIED: CUSTOMER RVUSA MANUF OTHER
INITIAL FLOW GREAT GOOD OKAY FAIR BAD N/A
CLEANING ISSUES SLOW FLOW HEAVY DEBRIS OBSTRUCTION NONE
TANK ODORS GREAT GOOD OKAY FAIR BAD N/A
OVERALL HEALTH/GRADE _____

GRAY TANK 1 SERVICED? YES NO SHWR GAL COMBO
TANK CAPACITY 65 VERIFIED: CUSTOMER RVUSA MANUF OTHER
INITIAL FLOW GREAT GOOD OKAY FAIR BAD N/A
MOLD LEVEL MILD (1) MODERATE (2) HEAVY (3) NONE
TANK ODORS GREAT GOOD OKAY FAIR BAD N/A
OVERALL HEALTH/GRADE C Mold growth

GRAY TANK 2 SERVICED? YES NO SHWR GAL COMBO
TANK CAPACITY _____ VERIFIED: CUSTOMER RVUSA MANUF OTHER
INITIAL FLOW GREAT GOOD OKAY FAIR BAD N/A
MOLD LEVEL MILD (1) MODERATE (2) HEAVY (3) NONE
TANK ODORS GREAT GOOD OKAY FAIR BAD N/A
OVERALL HEALTH/GRADE _____

GRAY TANK 3 SERVICED? YES NO SHWR GAL COMBO
TANK CAPACITY _____ VERIFIED: CUSTOMER RVUSA MANUF OTHER
INITIAL FLOW GREAT GOOD OKAY FAIR BAD N/A
MOLD LEVEL MILD (1) MODERATE (2) HEAVY (3) NONE
TANK ODORS GREAT GOOD OKAY FAIR BAD N/A
OVERALL HEALTH/GRADE _____

WATER HEATER TANK REPORT

WH SERVICED? YES NO O/D
MANUF _____ TANK CAPACITY _____
ANODE 4.5" 9.5" NONE
ANODE CONDITION GOOD OK BAD
ANODE ADDED REPLACED N/A
CORROSION MILD HEAVY NONE
RUST MILD HEAVY NONE
OVERALL HEALTH/GRADE _____
REPLACE ANODE 3 M 6 M 12 M

NOTES & COMMENTS

Solution will help mold growth in gray.

HOLDING TANK CHARGE \$ _____
WATER HEATER CHARGE \$ _____
ANODE CHARGE \$ _____
CLOG CHARGE \$ _____
OTHER SERVICE \$ _____
TRAVEL CHARGE \$ _____
PRODUCT PURCHASE \$ 275.00

DISCOUNT 25.00 (\$ 250.00)

TAXES DUE \$ _____
TOTAL DUE \$ 200.00

CUSTOMER SIGNATURE [Signature]
By signing, I approve the work and charges outlined above.
Thank you for using Kleen Tank!

E-PAYMENT CARD CASH CHECK